



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN No. Z 142C/10a

1. MODELS AFFECTED: All Z 142C aircraft
2. SUBJECT: Increased stress of the V 500 P 7900-611 propeller flange, caused by the execution of spins with the engine power, must be prevented.
3. CORRECTION:
 1. Prohibition of intentional power on spins.
 2. Replacement of pages in the Airplane Flight Manual.
4. TIME OF COMPLIANCE: Immediately after the Bulletin receipt.
5. CORRECTION PERFORMED BY: The user.
6. EXPENSES COVERED BY: No expenses will arise.
7. NECESSARY MATERIAL: New pages of the Z 142C AFM dated from August 31, 1995 are enclosed to this Bulletin.
8. PROCEDURE: Replace original pages by the new ones and enter this revision into the Record of revisions.
9. THIS BULLETIN IS EFFECTIVE FROM THE DATE OF APPROVAL BY THE CIVIL AVIATION INSPECTORATE.
10. ENCLOSURES: New pages of the Z 142C AFM:
0-5, 1-3/1-4, 2-11/2-12


Ing. Antonín Partika

.....
Manufacturer's
Representative


Ing. Milan Vyhnálek

.....
CAI Representative

23. 11. 1995
.....
Date of approval by the CAI

CONTACT ADDRESS: **ZLIN AIRCRAFT a.s.**
ZLIN Service
765 81 OTROKOVICE
CZECH REPUBLIC