



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**


MANDATORY SERVICE BULLETIN No. Z 142C/12a

1. **MODELS AFFECTED:** All Z 142C aircraft.
2. **SUBJECT:** The Z 142C Maintenance Manual provides procedures for check and possible repairs of the wing attachment fittings. The appropriate procedure, necessary jigs and tools for the mentioned repair are specified in MD No. 6.203 - "Reaming the Holes in the Wing Main Attachment Fittings".
3. **CORRECTION:** Supplementation of MD No. 6.203 - "Reaming the Holes in the Wing Main Attachment Fittings" in the Z 142C Maintenance Manual - Vol. II.
4. **TIME OF COMPLIANCE:** Immediately after this Bulletin receipt.
5. **CORRECTION PERFORMED BY:** The Operator of aircraft.
6. **EXPENSES COVERED BY:** No expenses will arise.
7. **PROCEDURE:** In the Z 142C Maintenance Manual - Vol. II:
 - a) Remove old pages:
0-1, 0-3/0-4, 0-5, 0-7, 3-9/3-10, 6-1/6-2,
7-31/7-32, 7-33/7-34, 7-35/7-36, 7-37/7-38,
7-39/7-40, 7-41/7-42, 7-43.
 - b) Insert new pages marked with Rev. Sep 10, 1996:
0-1, 0-3/0-4, 0-5, 0-7, 3-9/3-10, 6-1/6-2,
6-72a/6-72b, 6-72c/6-72d, 6-72e/6-72f,
7-31/7-32, 7-33/7-34, 7-35/7-36, 7-37/7-38,
7-39/7-40, 7-41/7-42, 7-43/7-44, 7-45.
 - c) Enter accomplishing of this revision into the List of Revisions on page 0-7.
8. **NECESSARY MATERIAL:** New pages of the Z 142C Maintenance Manual - Vol. II will be delivered together with this Bulletin by the Manufacturer of aircraft.

9. THIS BULLETIN IS EFFECTIVE FROM THE DATE OF APPROVAL BY THE CIVIL AVIATION INSPECTORATE.
10. ENCLOSURE: New pages of the Z 142C Maintenance Manual - Vol. II: according to Sect. 7 of this Bulletin.



Dipl. Eng. František Tížek
Manufacturer's Representative



Dipl. Eng. Milan Vyhnálek
CAI Prague

July 10, 1996

Date of Approval by CAI

CONTACT ADDRESS:

ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 OTROKOVICE
CZECH REPUBLIC