



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 143L/18a

Engineering Aspects are CAA
of the Czech Republic Approved

1. **DATE:** March 5th, 1998

2. **MODELS
AFFECTED:** Z 143L airplanes S/N 0020 and 0021.

3. **SUBJECT:** To facilitate handling the Airplane Flight Manual, Doc. No. 005.012.US, the original plastic spiral binding of the Manual has been replaced by the new six-ring loose-leaf binder.

Considering that at prospective next revisions of the Airplane Flight Manual, Doc. No. 005.012.US, the new pages determined for replacement will be delivered in perforated condition, intended for fixing into the loose-leaf binder, it is necessary to replace previously delivered Z 143L Airplane Flight Manuals provided with the plastic spiral binding by the new ones.

4. **CORRECTION:** Replacement of the appropriate Airplane Flight Manual.

5. **TIME OF
COMPLIANCE:** Immediately after receipt of the Bulletin.

6. **CORRECTION
PERFORMED BY:** User.

7. **EXPENSES
COVERED BY:** Not applicable.

8. **PROCEDURE:** Replace the Z 143L AFM, Doc. No. 005.012.US, delivered originally along with the Z 143L airplane by the new AFM of the same Doc. No. given in the new loose-leaf binder. Cancel the original AFM with the plastic spiral binding.

9. **NECESSARY MATERIAL:** The Z 143L AFM, Doc. No. 005.012.US (the six-ring loose-leaf binding) - delivered by the Manufacturer of airplane.
10. **ENCLOSURES:** According to point 9 of this Bulletin.


Josef Kolář

Manufacturer's Representative

Contact address: ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 OTROKOVICE
CZECH REPUBLIC