

MANDATORY SERVICE BULLETIN Z 43/50a

Technical content of the document is approved
on the basis of DOA Approval No. EASA.21J.110

1. **DATE:** January 27, 2010
2. **APPLICABLE TO:** All Z 43 aircraft
3. **REASON:** Substitution of taxi and landing lights
4. **ACTIONS REQUIRED:** Pertinent revision of accompanying documentation - supplementation of the Directive for replacement of lights
5. **ACCOMPLISHMENT:** Immediately after receipt of this bulletin
6. **PERFORMED BY:** Operator/owner
7. **COSTS COVERED BY:** Operator/owner
8. **PROCEDURES:**
 - a) In Repair Manual of the Z 43 aircraft - valid up to S/N 0084 incl. - date of issue 1980 - czech version:
 - remove old pages: 1, 3, 205
 - insert new pages of Revision No. 12 with date of issue 14. 12. 2009
 - note this revision into the Log of revision
 - b) In Repair Manual of the Z 43 aircraft - valid from S/N 0085 incl. - date of issue 1996 - czech version:
 - remove old pages: 0-1, 0-3, 5-1,
 - insert new pages of Revision No. 10 with date of issue 14. 12. 2009
 - note this revision into the Log of revision
9. **MATERIAL:** New pages of accompanying documentation (see Enclosure)
10. **ENCLOSURES:**

New pages of Z 43 aircraft Repair Manual - valid up to S/N 0084 incl. - date of issue 1980:
1, 3, 205, 308A

New pages of Z 43 aircraft Repair Manual - valid from S/N 0085 incl. - date of issue 1996:
0-1, 0-3, 5-1, 5-122



.....
Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN SERVICE
765 81 Otrokovice
Czech Republic