



**ZLIN AIRCRAFT a.s.**  
Letiště 1578, 765 81 Otrokovice,  
Czech Republic  
e-mail: zlin-service@zlinaircraft.eu  
http://www.zlinaircraft.eu

**MANDATORY**

**SERVICE  
BULLETIN**


MANDATORY SERVICE BULLETIN Z 50/38a

Engineering Aspects are CAI  
of Czech Republic Approved

1. DATE: March 24, 1997
2. SUBJECT: Reprint of Textron Lycoming Mandatory Service Bulletin No. 526.
3. MODELS AFFECTED: All Zlin 50LS, 50LX, and 50LE aircraft with Textron Lycoming engine model AEIO-540-L1B5D.
4. TIME OF COMPLIANCE: Same as that required for Mandatory Service Bulletin No. 526.

Textron Lycoming Mandatory Service bulletin No. 526 is reprinted in its entirety as follows. Moravan a.s. requires compliance with this Mandatory Service Bulletin.

This reprint is current at the time Service Bulletin Z 50/38a is issued. However, when complying with this Service Bulletin, insure that this reprint of Textron Lycoming Mandatory Service Bulletin No. 526 is still current at time of compliance.

  
Josef Kolář

.....  
Manufacturer's  
Representative

Contact Address: ZLIN AIRCRAFT a.s.  
ZLIN Service  
765 81 Otrokovice  
CZECH REPUBLIC