

Datum stažení: 14.03.2013



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

**SERVICE
LETTER**

**Service Letter No. L 106
November 1, 2011**

MODELS AFFECTED: **Z 50LS aircraft, S/N 045, reg. ZS-OKZ**

SUBJECT: **Rubber dampers of the instrument board**

With respect to experiences from aircraft operation, we permit replacing cylindrical washers LN-0365 in hinges of the instrument board on condition, i.e. when they are worn, cracked or dry-rotted, or when rubber part is separated from metal part of the damper.

It means that the dampers need not be replaced at each 100 hour inspection as prescribed in Note (2) in the Technical Manual Z 50LS on Page 111.

A handwritten signature in blue ink, appearing to read 'Totek', written over a horizontal dotted line.

Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 Otrokovice
Czech Republic