

MANDATORY SERVICE BULLETIN Z 242L/62a Rev.1

Technical content of the document is
Approved on the basis of
DOA Approval No. EASA.21J.110

- 1. DATE:** January 15, 2015
- 2. MODEL AFFECTED:** All Z 242L aircraft.
- 3. SUBJECT:** There were detected bugs in the accompanying documentation issued by Mandatory Service Bulletin Z242L/62a, which were fixed now.
- 4. CORRECTION:** Pertinent correction of Z 242L aircraft MM Vol. I and MM Vol. II.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of this bulletin
- 6. PERFORMED BY:** Operator/owner.
- 7. COSTS COVERED BY:** No will arise.
- 8. PROCEDURES:**
 - a) In Maintenance Manual of the Z 242L, Vol. I (Doc. No. 003.021.1- czech version:
 - remove pages 5-5, 5-7, 5-10 of Revision No. 20 with date of issue 1.6.2013 and old page 1-8
 - insert corrected pages 5-5, 5-7, 5-10 and new page 1-8 of Revision No. 20 with date of issue 1.6.2013Note: corrections are marked by vertical line

- b) In Maintenance Manual of the Z 242L, Vol. I
(Doc. No. 003.022.1 - english version:
remove pages of Revision No. 20: 5-5, 5-7, 5-10
with date of issue 1.6.2013 and old page 1-8
– insert corrected pages 5-5, 5-7, 5-10 and new
page 1-8 of Revision No. 20 with date of issue
1.6.2013
Note: corrections are marked by vertical line
- c) In Maintenance Manual of the Z 242L, Vol. II
(Doc. No. 003.031.1- czech version:
– remove pages 0-3, 0-7 of Revision No. 10 with
date of issue 1.6.2013
– insert corrected pages 0-3, 0-7 of Revision No.
10 with date of issue 1.6.2013
Note: corrections are marked by vertical line
- d) In Maintenance Manual of the Z 242L, Vol. II
(Doc. No. 003.032.1 - english version:
remove pages 0-3, 0-7 of Revision No. 9 with
date of issue 1.6.2013
– insert corrected pages 0-3, 0-7 of Revision No.
9 with date of issue 1.6.2013
Note: corrections are marked by vertical line

**9. NECESSARY
MATERIAL:**

Corrected pages of accompanying documentation (see
Enclosure)

10. ENCLOSURES:

Corrected pages of Maintenance Manual of the Z
242L, Vol. I (Doc. No. 003.021.1) - czech version:
1-8, 5-5, 5-7, 5-10

Corrected pages of Maintenance Manual of the Z
242L, Vol. I (Doc. No. 003.022.1) - english version:
1-8, 5-5, 5-7, 5-10

Corrected pages of Maintenance Manual of the Z
242L, Vol. II (Doc. No. 003.031.1) - czech version:
0-3, 0-7

Corrected pages of Maintenance Manual of the Z
242L, Vol. II (Doc. No. 003.032.1) - english version:
0-3, 0-7



.....
Ing. Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
765 02 Otrokovice
Česká republika
www.zlinaircraft.eu