

MANDATORY SERVICE BULLETIN Z 242L/64a

Technical content of the document is approved
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** October 24, 2014
- 2. APPLICABLE TO:** All Z 242L aircraft
- 3. REASON:** Implementation of replacement of broken windshield of sliding canopy in aircraft operation.
- 4. ACTIONS REQUIRED:** Pertinent revision of Z 242L aircraft accompanying documentation
- 5. ACCOMPLISHMENT:** Immediately after receipt of this bulletin
- 6. PERFORMED BY:** Operator/owner
- 7. COSTS COVERED BY:** No will arise
- 8. PROCEDURES:**
 - a) In Maintenance Manual of the Z 242L, Vol. I (Doc. No. 003.021.1) - Czech version:
 - remove old pages: 0-3, 0-4, 0-6, 7-21
 - insert new pages of Revision No. 21 with date of issue 24.10.2014 (see Enclosure)
 - note this revision into the List of Revision
 - b) In Maintenance Manual of the Z 242L, Vol. I (Doc. No. 003.022.1) - English version:
 - remove old pages: 0-3, 0-4, 0-6, 7-21
 - insert new pages of Revision No. 21 with date of issue 24.10.2014 (see Enclosure)
 - note this revision into the List of Revision

- c) In Maintenance Manual of the Z 242L, Vol. II (Doc. No. 003.031.1) - Czech version:
 - remove old pages: 0-3, 0-4, 0-5, 0-8, 3-3, 6-1, 6-74A, 6-74B
 - insert new pages of Revision No. 12 with date of issue 24.10.2014 (see Enclosure).
 - note this revision into the List of Revision

- d) In Maintenance Manual of the Z 242L, Vol. II (Doc. No. 003.032.1) - English version:
 - remove old pages: 0-3, 0-4, 0-5, 0-8, 3-3, 6-1, 6-74A, 6-74B
 - insert new pages of Revision No. 11 with date of issue 24.10.2014 (see Enclosure).
 - note this revision into the List of Revision

9 NECESSARY MATERIAL:

New pages of accompanying documentation (see Enclosure)

10 PŘÍLOHY:

New pages of Z 242L aircraft Maintenance Manual, Vol. I (Doc. No. 003.021.1) – Czech version:
0-3, 0-4, 0-6, 7-21

New pages of Z 242L aircraft Maintenance Manual, Vol. I (Doc. No. 003.022.1) - English version:
0-3, 0-4, 0-6, 7-21

New pages of Z 242L aircraft Maintenance Manual, Vol. II (Doc. No. 003.031.1) – Czech version:
0-3, 0-4, 0-5, 0-8, 3-3, 6-1, 6-74A, 6-74B

New pages of Z 242L aircraft Maintenance Manual, Vol. II (Doc. No. 003.032.1) - English version:
0-3, 0-4, 0-5, 0-8, 3-3, 6-1, 6-74A, 6-74B



.....
Ing. Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
765 02 Otrokovice
Czech republic
www.zlinaircraft.eu