



## **MANDATORY SERVICE BULLETIN Z 242L/69a**

Technical content of the document is approved  
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE** February 25, 2017
- 2. MODEL AFFECTED:** All Z 242 L aircraft.
- 3. SUBJECT:** Formal correction of Airplane Flight Manual on the basis of aircraft design modification.
- 4. CORRECTION:** Pertinent revision of Z 242 L aircraft accompanying documentation
- 5. ACCOMPLISHMENT:** Immediately after receipt of this bulletin
- 6. PERFORMED BY:** Operator
- 7. COSTS COVERED BY:** No will arise
- 8. PROCEDURES:**
  - a) Flight Manual Z 242 L, (Doc. No. 003.011.1) – Czech language
    - remove old pages 0-1, 0-5, 0-7, 0-9, all pages of Chapter 7
    - insert new pages marked by REVISION No. 3 with date of issue 25.2.2017 (see Enclosures)
    - note this revision into the List of revisions
  -



**b) Flight Manual Z 242 L, (Doc. No. 003.012.1) – English language**

- remove old pages 0-1, 0-5, 0-7, 0-9, all pages of Chapter 7
- insert new pages marked by REVISION No. 3 with date of issue 25.2.2017 (see Enclosures)
- note this revision into the List of revisions

**9. NECESSARY MATERIAL:** New pages of accompanying documentation (see Enclosures)

**10. ENCLOSURES:**

a) Flight Manual Z 242 L, (Doc. No. 003.011.1) – Czech language

0-1, 0-5, 0-7, 0-9, 7-1 to 7-36

b) Flight Manual Z 242 L, (Doc. No. 003.012.1) – English language

0-1, 0-5, 0-7, 0-9, 7-1 to 7-36

.....  
**Ing. Aleš Hanzal**  
Head of DOA

**Contact address:** ZLIN AIRCRAFT a.s.  
765 02 Otrokovice  
Czech republic