



MANDATORY SERVICE BULLETIN Z 242L/65a

SAFETY RELATED

Technical content of the document
Approved by the EASA Nr. 10060706

- 1. DATE** January 13, 2017

- 2. MODEL AFFECTED:** All Z 242 L aircraft with strengthened wings without AMU1 Acceleration monitoring unit installation (*aircraft's S/N from 0657 to S/N 0746 incl., which the additional installation of AMU1.01 acc. to MSB Z242L/44a or Z242L/52a has not been performed*).

- 3. SUBJECT:** Change of aircraft airworthiness limitation with strengthened wings without AMU1 Acceleration monitoring unit installation in UTILITY, AEROBATIC category.

- 4. CORRECTION:** Pertinent revision of Z 242 L aircraft accompanying documentation

Pertinent change of limitations mentioned in Mandatory Service Bulletin Z242L/52a, sect. 4.1.3.

- 5. ACCOMPLISHMENT:** Immediately after receipt of this bulletin

- 6. PERFORMED BY:** Operator

- 7. COSTS COVERED BY:** No will arise



8. PROCEDURES:

- a) Maintenance Manual Z 242 L, Vol. I (Doc. No. 003.021.1)**
– Czech language
- remove old pages 0-3, 0-4, 0-6, 9-1, 9-2, 9-3, 9-4, 9-5, 9-6, 9-7, 9-8
- insert new pages marked by REVIZE č. 22 with date of issue 15.3.2016 (see Enclosures)
- note this revision into the List of revisions

- b) Maintenance Manual Z 242 L, Vol. I (Doc. No. 003.022.1)**
– English language
- remove old pages 0-3, 0-4, 0-6, 9-1, 9-2, 9-3, 9-4, 9-5, 9-6, 9-7, 9-8
- insert new pages marked by REVISION No. 22 with date of issue 15.3.2016 (see Enclosures)
- note this revision into the List of revisions

- c) Supplement No. 1 to Mandatory Service Bulletin Z 242L/52a**
- print supplement No. 1 and insert it to the bulletin Z 242L/52a with date of issue March 8, 2007.

- 9. NECESSARY MATERIAL:** New pages of accompanying documentation (see Enclosures)
Supplement No. 1 to Mandatory Service Bulletin Z242L/52a

ZLIN AIRCRAFT

Letiště 1887
765 02 Otrokovice

www.zlinaircraft.eu



10. ENCLOSURES:

- a) Maintenance Manual Z 242 L, Vol. I (Doc. No. 003.021.1)
– Czech language
0-3, 0-4, 0-6, 9-1, 9-2, 9-3, 9-4, 9-5, 9-6, 9-7, 9-8
- b) Maintenance Manual Z 242 L, Vol. I (Doc. No. 003.022.1)
– English language
0-3, 0-4, 0-6, 9-1, 9-2, 9-3, 9-4, 9-5, 9-6, 9-7, 9-8
- c) Supplement No. 1 to Mandatory Service Bulletin
Z242L/52a

.....
Ing. Aleš Hanzal
Head of DOA

Contact address: ZLIN AIRCRAFT a.s.
765 02 Otrokovice
Czech republic