



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 142C/33a

Technical content of the document approved
on the basis of DOA Approval No. EASA.21J.110

1. **DATE:** April 10, 2007

2. **MODEL AFFECTED:** All Z 142C aircraft with AMU 1 acceleration Monitoring Unit installed.

3. **SUBJECT:** On the basis of Mandatory Service Bulletin No. Z 142C/32a, the Methods of data processing procedure for AMU 1.01 Acceleration Monitoring Unit have been revised. The rules for sending downloaded data to the manufacturer and other minor changes are included.

4. **CORRECTION:** Issue of revised Methods of Data Processing Procedure for AMU 1.01 Acceleration Monitoring Unit for aircraft of Z 42 series.

5. **TIME OF COMPLIANCE:** Immediately after receipt of this bulletin.

6. **PERFORMED BY:** Operator.

7. **COSTS COVERED BY:** No will arise.

8. **PROCEDURES:** Replace old Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit with the new marked by: Revision No. 1 with date April 10, 2007 (see Enclosure).

Cancel old Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit.

9. NECESSARY MATERIAL:

Method of data processing procedure for AMU 1.01
Acceleration Monitoring Unit for aircraft of Z 42 series
in Czech and English language (see Enclosure).

10. ENCLOSURES:

Method of data processing procedure for AMU 1.01
Acceleration Monitoring Unit for aircraft of Z 42 series
– Czech version: DOC.No.Z42.AMU1.091
+ form Z142C-AMU1/1; Z142C-AMU1/2

Method of data processing procedure for AMU 1.01
Acceleration Monitoring Unit for aircraft of Z 42 series
– English version: DOC.No.Z42.AMU1.092
+ form Z142C-AMU1/1; Z142C-AMU1/2



.....
Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 Otrokovice
Czech Republic