



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN No. Z 143L / 11a

Engineering Aspects are CAI
of the Czech Republic
Approved

1. DATE: December 5, 1996
2. MODELS AFFECTED: All Z 143L airplanes.
3. SUBJECT: Revision of Z 143L Maintenance Manual, Vol.I, related to Revisions Nos. 3 and 4 of Z 143L Flight Manual and correction of formal failures in Z 143L MM, Vol.I found out by airplanes operators, airplane manufacturer and aviation authorities.
4. CORRECTION: Replacement of the present Z 143L MM, Vol.I [Doc. No. 005.022 (English version); 005.021 (Czech version)], Revision No.4 with a new one, with Revision No.5 included.
Note: date of Revision No.5 pages issuance
- September 2, 1996.
5. TIME OF COMPLIANCE: Immediately after receipt of this Bulletin.
6. CORRECTION PERFORMED BY: The user.
7. EXPENSES COVERED BY: No expenses arise.
8. PROCEDURE: Replace Z 143L MM, Vol.I, Revision No.4 with Z 143L MM, Vol.I, Revision No.5, enclosed to this Bulletin. Write S/N and registration mark of the airplane on the title page (0-1). Include Supplements to MM, Rev.4 (if used) into Section 9 of the MM, Rev.5.
Invalidate MM, Rev.4.


- 2 -

9. NECESSARY
MATERIAL:

Z 143L Maintenance Manual, Vol.I - Doc.
No. 005.022 (English version); 005.021
(Czech version) - Revision No.5 will be
delivered by the manufacturer together
with the Bulletin.

10. ENCLOSURES:

Z 143L Maintenance Manual, Vol.I - Doc.
No. 005.022 (English version); 005.021
(Czech version) - Revision No.5.



Dipl. Eng. František Tížek

Manufacturer's Representative

CONTACT ADDRESS:

ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 OTROKOVICE
CZECH REPUBLIC