



**ZLIN AIRCRAFT a.s.**  
Letiště 1578, 765 81 Otrokovice,  
Czech Republic  
e-mail: [zlin-service@zlinaircraft.eu](mailto:zlin-service@zlinaircraft.eu)  
<http://www.zlinaircraft.eu>

**MANDATORY**

**SERVICE  
BULLETIN**

## **MANDATORY SERVICE BULLETIN Z 143L/33a**

Technical content of the document approved  
on the basis of DOA Approval No. EASA.21J.110

1. **DATE:** February 15, 2007
2. **MODEL AFFECTED:** All Z 143 L aircraft, which are provided with the Flight Manual DOC.No.005.013.
3. **SUBJECT:** As the changes of Flight Manual have been recently performed in Czech English and U.S. versions only, the German version of the Flight Manual has not been kept updated. It has been therefore currently performed a complex revision of German Flight Manual, where all missing changes from Czech, English and U.S. versions of the Z 143L Flight Manual have been incorporated.
4. **CORRECTION:** Pertinent revision of accompanying documentation (Flight Manual)
5. **TIME OF COMPLIANCE:** Immediately after receipt of this bulletin.
6. **PERFORMED BY:** Operator.
7. **COSTS COVERED BY:** Operator.
8. **PROCEDURES:**
  - a) In the Z 143L Flight Manual, DOC.NO.005.013 – German version:
    - remove old pages: 0-1; 0-8; 0-9; 0-10; 0-12; 1-3; 1-13; 2-6; 2-7; 2-9; 2-10 (S/N 0022); 2-10 (S/N 0023); 2-11; 2-12; 2-13; 2-14; 2-17; 2-21; 2-22; 2-24; 3-14; 3-17; 3-18; 3-19; 3-20; 3-21; 3-22; 4-3; 4-7; 4-8 (S/N 0022); 4-8 (S/N 0023); 4-9; 4-10 (S/N 0022); 4-10 (S/N 0023); 4-11; 4-14; 4-24; 4-32; 4-34; 4-35; 6-15; 6-16; 6-17; 6-20; 6-21; 6-23; 6-24; 7-12; 7-13; 7-15; 7-16; 7-17; 7-18; 7-19; 7-20; 7-21; 7-24; 7-36 (S/N 0022); 7-36 (S/N 0023); 7-37; 7-39; 7-42; 7-44; 7-45; 7-50; 8-3; 8-4; 8-9; 8-10 (S/N 0022); 8-10 (S/N 0023).
    - insert new pages of the Revision No. 3 with date 21.11.2007 (see Enclosure)
    - note this revision into the Log of Revision
  - b) Order new placard with design speeds (FM page 2 – 21) at aircraft manufacturer and stick it on cockpit glass instead of the original one.

**9. NECESSARY MATERIAL:**

New pages of accompanying documentation (see Enclosure).  
New placard with design speeds.

**10. ENCLOSURES:**

New pages the Z 143L aircraft Flight Manual,  
DOC.No.005.013 - German version:  
0-1; 0-8; 0-9; 0-10; 0-12; 1-3; 1-13; 2-6; 2-7; 2-9; 2-10; 2-10a;  
2-10b; 2-11; 2-12; 2-13; 2-14; 2-17; 2-21; 2-22; 2-24; 3-14;  
3-17; 3-18; 3-19; 3-20; 3-21; 3-22; 4-3; 4-7; 4-8; 4-9; 4-10;  
4-11; 4-14;  
4-24; 4-32; 4-34; 4-35; 4-35a; 4-35b; 6-15; 6-16; 6-17; 6-17a;  
6-17b; 6-20; 6-21; 6-23; 6-24; 7-12; 7-12a; 7-12b; 7-13; 7-13a;  
7-13b; 7-15; 7-16; 7-17; 7-18; 7-19; 7-20; 7-20a; 7-20b; 7-21;  
7-24; 7-36; 7-37; 7-39; 7-39a; 7-39b; 7-42; 7-44; 7-45; 7-45a;  
7-45b;  
7-50; 8-3; 8-4; 8-9; 8-10.

SIGNED:



.....  
**Dušan Totek**  
Chief Designer

**Contact address:** ZLIN AIRCRAFT a.s.  
ZLIN Service  
765 81 Otrokovice  
Czech Republic