



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 143 LSi/5a

Technical content of the document is approved
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** April 6, 2010
- 2. APPLICABLE TO:** All Z 143 LSi aircraft equipped with:
 - Towing gear with TOST E-85 tow release acc. to Drwg. No. L143.8410and (or)
 - S-TEC 55 or S-TEC 55X Autopilot installation
- 3. REASON:** Issue of revised supplement of Z 143 LSi Aircraft Flight Manual for Towing gear with TOST E-85 tow release and issue of revisited supplements of Z 143 LSi Aircraft Flight Manual and Maintenance Manual for S-TEC 55, 55X Autopilot installation, approved by EASA.
- 4. ACTIONS REQUIRED:** Issue of revised Z 143 LSi aircraft accompanying documentation.
- 5. ACCOMPLISHMENT:** Immediately after receipt of this bulletin
- 6. PERFORMED BY:** Operator/owner.
- 7. COSTS COVERED BY:** Operator/owner.
- 8. PROCEDURES:**
 - a) In Aircraft Flight Manual of the Z 143 LSi (Doc. No. Si005.011) - Czech version:
 - remove old supplement No. 3a (approved by DOA organization with date Nov. 28, 2007) with date of issue Nov. 22, 2007
 - remove old supplement No. 10 (approved by DOA organization with date Apr 14, 2009) with date of issue Apr. 10, 2009
 - remove old supplement No. 11 (approved by DOA organization with date May 28, 2007) with date of issue May 21, 2007

MANDATORY SERVICE BULLETIN Z 143 LSi/5a

- insert new supplement No. 3a (approved by EASA with date 16.3.2010) with date of issue Nov. 10, 2009.
- insert new supplement No. 10 (approved by EASA with date 31.3.2010) with date of issue Nov. 10, 2009.
- insert new supplement No. 11 (approved by EASA with date 31.3.2010) with date of issue Nov. 10, 2009.
- note this revision into the List of revision

b) In Aircraft Flight Manual of the Z 143 LSi (Doc. No Si005.012) - English version:

- remove old supplement No. 3a (approved by DOA organization with date Nov 28, 2007) with date of issue Nov. 22, 2007.
- remove old supplement No. 10 (approved by DOA organization with date Apr 14, 2009) with date of issue Apr. 10, 2009
- remove old supplement No. 11 (approved by DOA organization with date May 28, 2007) with date of issue May 21, 2007
- insert new supplement No. 3a (approved by EASA with date 16.3.2010) with date of issue Nov. 10, 2009.
- insert new supplement No. 10 (approved by EASA with date 31.3.2010) with date of issue Nov. 10, 2009.
- insert new supplement No. 11 (approved by EASA with date 31.3.2010) with date of issue Nov. 10, 2009.
- note this revision into the List of revision

c) In Aircraft Maintenance Manual of the Z 143 LSi (Doc. No. Si005.021.1) - Czech version:

- remove old supplement No. 10 with date of issue 2009-04-07
- remove old supplement No. 11 with date of issue 2007-05-25
- insert new supplement No. 10 with date of issue 2009-11-10
- insert new supplement No. 11 with date of issue 2009-11-10
- note this revision into the List of revision

d) In Aircraft Maintenance Manual of the Z 143 LSi (Doc. No. Si005.022.1) - English version:

- remove old supplement No. 10 with date of issue 2009-04-07
- remove old supplement No. 11 with date of issue 2009-03-17
- insert new supplement No. 10 with date of issue 2009-11-10
- insert new supplement No. 11 with date of issue 2009-11-10
- note this revision into the List of revision

9. NECESSARY MATERIAL: New supplement No. 3a, No. 10, No. 11 of Z 143 LSi Aircraft Flight Manual in Czech and English version (see Enclosure).

New supplement No. 10, No. 11 of Z 143 LSi Aircraft Maintenance Manual in Czech and English version (see Enclosure).

10. ENCLOSURES:

New supplement No. 3a of Z 143 LSi Aircraft Flight Manual, (Doc. No. Si005.011) - Czech version, (Approved by EASA with date 16.3.2010) with date of issue Nov. 10, 2009

New supplement No. 3a of Z 143 LSi Aircraft Flight Manual, (Doc. No. Si005.012) - English version, (Approved by EASA with date 16.3.2010) with date of issue Nov. 10, 2009

New supplement No. 10 of Z 143 LSi Aircraft Flight Manual, (Doc. No. Si005.011) - Czech version, (Approved by EASA with date 31.3.2010) with date of issue Nov. 10, 2009

New supplement No. 10 of Z 143 LSi Aircraft Flight Manual, (Doc. No. Si005.012) - English version, (Approved by EASA with date 31.3.2010) with date of issue Nov. 10, 2009

New supplement No. 11 of Z 143 LSi Aircraft Flight Manual, (Doc. No. Si005.011) - Czech version, (Approved by EASA with date 31.3.2010) with date of issue Nov. 10, 2009

New supplement No. 11 of Z 143 LSi Aircraft Flight Manual, (Doc. No. Si005.012) - English version, (Approved by EASA with date 31.3.2010) with date of issue Nov. 10, 2009

New supplement No. 10 of Z 143 LSi Aircraft Maintenance Manual, (Doc. No. Si005.021.1) - Czech version, with date of issue Nov. 10, 2009

New supplement No.10 of Z 143 LSi Aircraft Maintenance Manual (Doc. No. Si005.022.1) - English version, with date of issue Nov. 10, 2009

New supplement No. 11 of Z 143 LSi Aircraft Maintenance Manual (Doc. No. Si005.021.1) - Czech version, with date of issue Nov. 10, 2009

New supplement No. 11 of Z 143 LSi Aircraft Maintenance Manual (Doc. No. Si005.022.1) - English version, with date of issue Nov. 10, 2009



.....
Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN SERVICE
765 81 Otrokovice
Czech Republic