



**ZLIN AIRCRAFT a.s.**  
Letiště 1578, 765 81 Otrokovice,  
Czech Republic  
e-mail: [zlin-service@zlinaircraft.eu](mailto:zlin-service@zlinaircraft.eu)  
<http://www.zlinaircraft.eu>

**MANDATORY**

**SERVICE  
BULLETIN**

## **MANDATORY SERVICE BULLETIN Z 242L/45a**

Engineering Aspect are  
CAA Approved

- 1. DATE:** August 15, 2003
- 2. APPLICABLE TO:** All ZLIN Z 242L aircraft.
- 3. REASON:**
1. Supplement of list of parts with limited operation time for aircraft operation over 5500 flight hours.
  2. Formal arrangements of accompanying technical documentation.
- 4. ACTIONS REQUIRED:** In the Maintenance Manual of the Z 242L Aircraft:  
Vol I. (DOC. No. 003.021.1 - Czech version), (DOC. No. 003.022.1 - English version);  
Vol. II. (DOC. No. 003.031.1 - Czech version), (DOC. No. 003.032.1 - English version) replace pages, which are included as an Enclosure of this Bulletin.
- 5. ACCOMPLISHMENT:** Immediately after receipt of Bulletin.
- 6. PERFORMED BY:** Operator.
- 7. COSTS COVERED BY:** No expenses will arise.
- 8. NECESSARY MATERIAL:** New pages of the Maintenance Manual of the Z 242 L Aircraft Vol. I., Vol. II. (see Enclosure).
- 9. PROCEDURES:**
- a) In the Maintenance Manual of the Z 242L Aircraft-Vol. I:  
(DOC. No.003.021.1 - Czech version):  
Remove old pages: 0-3, 0-4, 0-6, 2-34, 4-26, 5-12, 6-1, 6-12, 6-13, 7-1, 7-34, 9-1, 9-2, 9-3, 9-4.  
Insert new pages marked with Revision No. 13, 15.8.2003 (see Enclosure).  
Note this revision into the List of Revisions.
  - b) In the Maintenance Manual of the Z 242L Aircraft-Vol. I:  
(DOC. No. 003.022.1 - English version):  
Remove old pages: 0-3, 0-4, 0-6, 2-34, 4-26, 5-12, 6-1, 6-12, 6-13, 9-1, 9-2, 9-3, 9-4.  
Insert new pages marked with Revision No. 13, Aug 15, 2003 (see Enclosure).  
Note this revision into the List of Revisions.
  - c) In the Maintenance Manual of the Z 242L Aircraft-Vol. II:  
(DOC. No. 003.031.1 - Czech version),  
Remove old pages: 0-3, 0-4, 0-5, 0-7, 1-12, 2-2, 2-7, 4-12, 6-1, 7-6.  
Insert new pages marked with Revision No. 5, 8.10.2003 (see Enclosure).  
Note this revision into the List of Revisions.
  - d) In the Maintenance Manual of the Z 242L Aircraft-Vol. II:  
(DOC. No. 003.032.1 - English version),  
Remove old pages: 0-3, 0-4, 0-5, 0-7, 1-12, 2-2, 2-7, 4-12, 6-1, 7-6.  
Insert new pages marked with Revision No. 4, Aug 15, 2003 (see Enclosure).  
Note this revision into the List of Revisions.

**10. ENCLOSURE:**

New pages of the Maintenance Manual of the Z 242 L Aircraft Vol. I.  
(DOC. No. 003.021.1 - Czech version):  
0-3, 0-4, 0-6, 2-34, 4-26, 5-12, 6-1, 6-10A, 6-10B, 6-10C, 6-10D, 6-12, 6-13,  
7-1, 7-34, 9-1, 9-2, 9-3, 9-4.

New pages of the Maintenance Manual of the Z 242 L Aircraft Vol. I.  
(DOC. No. 003.022.1 - English version):  
0-3, 0-4, 0-6, 2-34, 4-26, 5-12, 6-1, 6-10A, 6-10B, 6-10C, 6-10D, 6-12, 6-13,  
9-1, 9-2, 9-3, 9-4.

New pages of the Maintenance Manual of the Z 242 L Aircraft Vol. II.  
(DOC. No. 003.031.1 - Czech version):  
0-3, 0-4, 0-5, 0-7, 1-12, 2-2, 2-7, 2-13A, 2-13B, 4-12, 6-1, 6-74A, 6-74B, 7-6.

New pages of the Maintenance Manual of the Z 242 L Aircraft Vol. II.  
(DOC. No. 003.032.1 - English version):  
0-3, 0-4, 0-5, 0-7, 1-12, 2-2, 2-7, 2-13A, 2-13B, 4-12, 6-1, 6-74A, 6-74B, 7-6.



.....  
Ing. Dušan TOTEK  
Chief Designer

**CONTACT ADDRESS:**

**ZLIN AIRCRAFT a.s.**  
Obchodne technicke sluzby  
765 81 Otrokovice  
Czech Republic