



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlinservice@zlinaircraft.eu
http://www.zlinaircraft.eu

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 242L/50a

Technical content of the document approved
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** December 14, 2006
- 2. MODEL AFFECTED:** All Z 242L aircraft with MORAVAN Glider Towing Equipment installation according to C142.8400 or L242.8440.
- 3. SUBJECT:** Supplements of the Z 242L aircraft Flight Manual (DOC.No.003.012) for towing gear have been revised due to inaccuracy in numeration and validity of single towing gear modification.
- 4. CORRECTION:** Replacement of appropriate supplement of Z 242L aircraft Flight Manual (DOC.No.003.011 or DOC.NO.003.012) behind the new.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of this bulletin.
- 6. PERFORMED BY:** Operator.
- 7. COSTS COVERED BY:** No will arise.
- 8. PROCEDURES:**
 - a) In the Z 242L aircraft Flight Manual (DOC.No.003.012) – English version:
 - In case of glider towing equipment installation acc. to C142.8400
 - remove old Supplement No. 1 with date 15.12.1993
 - insert new Supplement No. 1 with Revision No. 1 date 5. 4. 2006 (see Enclosure)
 - In case of glider towing equipment installation acc. to L242.8400
 - remove old Supplement No. 1b with date 25.10.1996
 - insert new Supplement No. 1b with Revision No. 1 with date 5. 4. 2006 (see Enclosure)

MANDATORY SERVICE BULLETIN Z 242L/50

- b) In the Z 242L aircraft Flight Manual (DOC.No.003.011) – Czech version:

In case of glider towing equipment installation acc. to C142.8400

- insert new Supplement No. 1 with Revision No. 1 date 5.4.2006 (see Enclosure)

In case of glider towing equipment insatallation acc. to L242.8400

- remove old Supplement No. 1b with date 25.10.1996
- insert new Supplement No. 1b with Revision No. 1 with date 5. 4. 2006 (see Enclosure)

9. NECESSARY MATERIAL:

New Supplements No. 1; 1b of the Z 242L aircraft Flight Manual (DOC.No.003.011) – Czech version (see Enclosure)
(DOC.No.003.012) – English version (see Enclosure).

10. ENCLOSURE:

Supplement No.1 – Glider/Banner Towing Equipment – C142.8400 – Czech version
Supplement No.1b – Glider/Banner Towing Equipment – L242.8400 – Czech version
Supplement No.1 – Glider/Banner Towing Equipment – C142.8400 – English version
Supplement No.1b – Glider/Banner Towing Equipment – L242.8400 – English version



.....
Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 Otrokovice
Czech Republic