Download date: 14.03.2013



ZLIN AIRCRAFT a.s. Letiště 1578, 765 81 Otrokovice, Czech Republic e-mail: zlinservice@zlinaircraft.eu

e-mail: zlinservice@zlinaircraft.eu http://www.zlinaircraft.eu



MANDATORY SERVICE BULLETIN Z 42/57a

Technical content of the document approved on the basis of DOA Approval No. EASA.21J.110

1. DATE: April 10, 2007

2. MODEL AFFECTED: All Z 42; Z 42M; Z 42MU aircraft with AMU 1 acceleration

Monitoring Unit installed.

3. SUBJECT: On the basic of Mandatory Service Bulletin No. Z 42/56a, the

Methods of data processing procedure for AMU 1.01 Acceleration Monitoring Unit have been revised. The rules for sending downloaded data to the manufacturer and other minor

changes are included.

4. CORRECTION: Issue of revised Methods of Data Processing Procedure for

AMU 1.01 Acceleration Monitoring Unit for aircraft of Z 42

series.

5. TIME OF COMPLIANCE: Immediately after receipt of this bulletin.

6. PERFORMED BY: Operator.

7. COSTS COVERED BY: No will arise.

8. PROCEDURES: Replace old Method of data processing procedure for

AMU 1.01 Acceleration Monitoring Unit with the new marked by: Revision No. 1 with date April 10, 2007 (see Enclosure).

Cancel old Method of data processing procedure for AMU 1.01

Acceleration Monitoring Unit.

MANDATORY SERVICE BULLETIN Z42/57a

9. NECCESSARY MATERIAL:

Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit for aircraft of Z 42 series in Czech and English language (see Enclosure).

10. ENCLOSURES:

Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit for aircraft of Z 42 series

Czech version: DOC.No.Z42.AMU1.091+ form Z42-AMU1/1; Z42-AMU1/2

Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit for aircraft of Z 42 series

English version: DOC.No.Z42.AMU1.092
 + form Z42-AMU1/1; Z42-AMU1/2

Dušan Totek Chief Designer

Contact address: ZLIN AIRCRAFT a.s.

ZLIN Service 765 81 Otrokovice Czech Republic