



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

SERVICE BULLETIN No. Z 50/41a, Z 50M/13a

Engineering Aspect are CAA
of Czech Republic Approved

1. DATE: June 9, 1997
2. MODELS
AFFECTED: All Z 50L, Z 50LA, Z 50LS, Z 50LX, Z 50LE and
Z 50M aircraft.
3. SUBJECT: The aforesaid aircraft with reached overall 900
flight hours are prescribed for the technical
inspection done after 300 + 15 flight hours from
the overhaul.
4. CORRECTION:
 - 4.1 Stated service life of 900 flight hours may be
exceeded by 15 flight hours considering the
tolerance of the technical inspections interval.
 - 4.2 Related revision of the data given in the Technical
Manuals.
5. TIME OF
COMPLIANCE: Correction 4.1 - when overall 900 flight hours are
reached.
Correction 4.2 - immediately after the Bulletin
receipt.
6. CORRECTION
PERFORMED BY: The Operator of aircraft.
7. EXPENSES
COVERED BY: No expenses will arise.
8. PROCEDURE:
 - 8.1 Replace old sheets with new ones dated Rev. Jun
14, 1997 in appropriate manuals:

In the Czech version:
 - Z 50L, LA Technical Description: pages 8, 100,
108;
 - Z 50LS Technical Description and Maintenance
Manual: pages 8, 104, 115;
 - Z 50LX Technical Description and Maintenance
Manual: pages 8, 104, 115;
 - Z 50LE Technical Description and Maintenance
Manual: pages 0-3, 0-5, 3-24, 3-35;
 - Z 50M Technical Description: pages 0-3, 0-5,
3-23, 3-33.

In the English version:

- . Z 50L, LA Technical Manual: pages 8, 100, 109;
- . Z 50LS Technical Manual: pages 8, 105, 117;
- . Z 50M Technical Manual: pages 0-3, 0-5, 3-29, 3-42.

In the German version:

- . Z 50LS Technical Description and Maintenance Manual: pages 8, 103, 114.

Enter and confirm this revision into the Log of Revisions.

- 8.2 Carry out the technical inspection prescribed to be done after 300 + 15 flight hours from the overhaul not later than when overall 915 flight hours are reached.

9. NECESSARY
MATERIAL:

New sheets acc. to point 8.1 of this Bulletin will be delivered along with the Bulletin by the Manufacturer of aircraft.

10. ENCLOSURE:

New sheets acc. to point 8.1 of this Bulletin.


Josef Kolář

.....
Manufacturer's
Representative

Contact Address:

ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 Otrokovice
Czech Republic