Download date: 14.03.2013



ZLIN AIRCRAFT a.s. Letiště 1578, 765 81 Otrokovice, Czech Republic

e-mail: zlinservice@zlinaircraft.eu http://www.zlinaircraft.eu



MANDATORY SERVICE BULLETIN Z 142C/36a

Technical content of the document approved on the basis of DOA Approval No. EASA.21J.110

1. DATE: September 23, 2010

2. MODEL AFFECTED: All Z 142C aircraft with AMU 1 Acceleration Monitoring Unit

installed.

3. SUBJECT: The Methods of data processing procedure for AMU 1.01

Acceleration Monitoring Unit with date of issue 1.4.2007 have

been revised.

4. CORRECTION: Issue of new revised document with a new name "Methods of

Data Processing Procedure for AMU 1.01 Acceleration

Monitoring Unit" with new date of issue 1.5.2010.

5. TIME OF COMPLIANCE: Immediately after receipt of this bulletin.

6. PERFORMED BY: Operator.

7. COSTS COVERED BY: No will arise.

8. PROCEDURES: Replace old Method of data processing procedure for

AMU 1.01 Acceleration Monitoring Unit with date of issue April 10, 2007 (see Enclosure) behind a new, marked by Doc. No. Z42.AMU1.092 with date of issue 1.5.2010 (see

Enclosure).

Cancel old Method of data processing procedure for AMU 1.01

Acceleration Monitoring Unit.

9. NECCESSARY MATERIAL:

New Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit in czech and english language (see Enclosure).

10. ENCLOSURES:

Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit in Czech language with date of issue 1.5.2010 is available for free on the web sites of aircraft manufacturer all holders of "bulletin service".

Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit in English language with date of issue 1.5.2010 is available for free on the web sites of aircraft manufacturer all holders of "bulletin service".

Dušan Totek Chief Designer

Contact address: ZLIN AIRCRAFT a.s.

ZLIN Service 765 81 Otrokovice Czech Republic