



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY BULLETIN Z 143L/ 22a

Engineering Aspect are
CAA Approved

- 1. DATE:** April 20, 2000
- 2. MODELS AFFECTED:** All ZLIN Z 143L Aircraft.
- 3. SUBJECT:** Formal adaptations, reminder from aircraft operation near of the user
- 4. CORRECTION:** In the Z 143L Maintenance Manual (Doc. No. 005.022.1) replace pages, which are included as an Enclosure of this Bulletin.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of Bulletin.
- 6. CORRECTION PERFORMED BY:** Operator.
- 7. EXPENSES COVERED BY:** No expenses will arise.
- 8. PROCEDURE:**
- a) In the Z 143L Maintenance Manual
Remove old pages: 01-1, 01-11, 01-12, 01-13, 01-14, 01-15, 01-19, 01-20, 01-24, 01-26, 01-33, 05-19, 05-20, 05-22, 05-27, 05-29, 05-31, 11-11, 11-12, 21-CONTENT, 21-1, 21-8, 23-1, 24-18, 24-19, 32-44, 32-48, 32-54, 34-10, 72-8, 72-11, 74-6, 91-23C.

Insert new pages marked with REVISION No.1, 2000-04-20 (see Enclosure).
 - b) Note this revision into the List of Revisions
- 9. NECESSARY MATERIAL:** New pages of the Z 143L Maintenance Manual (see Enclosure).
- 10. ENCLOSURE:** New pages in the Z 143L- Maintenance Manual : 01-1, 01-11, 01-12, 01-13, 01-14, 01-15, 01-19, 01-20, 01-24, 01-26, 01-33, 05-19, 05-20, 05-22, 05-27, 05-29, 05-31, 11-11, 11-12, 21-CONTENT, 21-1, 21-8, 23-1, 24-18, 24-19, 32-44, 32-48, 32-54, 34-10, 72-8, 72-11, 74-6, 91-23C.

Ing. Lubomír Hubený
Chief Designer

CONTACT ADDRESS: ZLIN AIRCRAFT a.s.
Obchodne technicke sluzby
765 81 Otrokovice
Czech Republic