



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY
SERVICE
BULLETIN

MANDATORY SERVICE BULLETIN Z 143L/28a – Rev. 1

Engineering Aspects are
CAA CZ Approved

1. **DATE:** January 14, 2005
2. **MODEL AFFECTED:** All aircraft Z 143 L on which nose landing gear type 793-HPK-185-19, 793-HPK-185-19-7 of manufacturer AXL, Inc. Semily, Czech Republic is installed.
3. **SUBJECT:** On-condition operation for nose landing gear type 793-HPK-185-19, 793-HPK-185-19-7.
4. **CORRECTION:**
 - a) Revision of operation on condition of the nose landing gear type 793-HPK-185-19, 793-HPK-185-19-7 – Cancel of performance of 50 hours inspection of nose landing gear.
 - b) Pertinent revision of accompanying documentation.
5. **TIME OF COMPLIANCE:** Immediately after receipt of bulletin.
6. **PERFORMED BY:** Operator.
7. **COSTS COVERED BY:** Operator.
8. **PROCEDURES:**
 - a) The Manual will be sent on operator's order.
 - b) In the maintenance Manual of the Z 143 L aircraft, DOC No. 005.021.1 – Czech version
 - remove old pages: 01-11; 01-12; 01-35; 05-17; 05-18
 - insert new pages marked with Revision No. 8 with date 2005-01-14 (see Enclosure)
 - note this revision into the List of revisions.

In the maintenance Manual of the Z 143 L aircraft,
DOC No. 005.022.1 – English version

- remove old pages: 01-11; 01-12; 01-35; 05-17; 05-18
- insert new pages marked with Revision No. 8 with date 2005-01-14
(see Enclosure)
- note this revision into the List of revisions.

**9. NECESSARY
MATERIAL:**

- a) On-condition maintenance and operation Manual of nose landing gear Type 793-HPK-185-19, 793-HPK-185-19-7 in Czech or English language version with date of issue June 10, 2003.
- b) New pages of accompanying documentation.

10. ENCLOSURE:

- a) On-condition maintenance and operation Manual of nose landing gear type 793-HPK-185-19, 793-HPK-185-19-7 in Czech or English language version with date of issue June 10, 2003.
- b) New pages of maintenance Manual of the Z 143 L aircraft, DOC No. 005.021.1 – Czech version:
01-11; 01-12; 01-35; 05-17; 05-18.

New pages of maintenance Manual of the Z 143 L aircraft,
DOC No. 005.022.1 – English version:
01-11; 01-12; 01-35; 05-17; 05-18.

SIGNED:



.....
Dušan Totecký
Chief Designer

Contact address:

ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 Otrokovice
Czech Republic

AXL, Inc.
ul. 3. května 800
513 01 Semily
Czech republic