



**ZLIN AIRCRAFT a.s.**  
Letiště 1578, 765 81 Otrokovice,  
Czech Republic  
e-mail: [zlin-service@zlinaircraft.eu](mailto:zlin-service@zlinaircraft.eu)  
<http://www.zlinaircraft.eu>

**MANDATORY**

**SERVICE  
BULLETIN**

## **MANDATORY SERVICE BULLETIN Z 143L/32a**

Technical content of the document approved  
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** December 5, 2007
- 2. MODEL AFFECTED:** All Z 143 L aircraft.
- 3. SUBJECT:** Accompanying documentation formal faults correct detected at aircraft operation.
- 4. CORRECTION:** Pertinent revision of accompanying documentation.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of bulletin.
- 6. PERFORMED BY:** Operator.
- 7. COSTS COVERED BY:** No will arise.
- 8. PROCEDURES:**
  - a) In the Z 143 L aircraft Flight Manual (č.DOK.005.011)
    - Czech version:
    - remove old pages: 0-1; 0-9; 0-10; 0-11; 0-12; 0-13; 0-15; 1-3; 2-4; 2-5; 2-12; 2-13; 2-15; 4-6 (S/N 0022); 4-6 (S/N 0023); 4-8 (S/N 0022); 4-8 (S/N 0023); 6-16; 6-17; 6-18; 6-19; 6-20; 6-21; 6-22; 6-23; 6-24; 6-25; 7-19; 8-3; 8-4; 8-9 (S/N 0022); 8-9a (S/N 0022); 8-9b (S/N 0022); 8-9 (S/N 0023)
    - insert new pages marked by Revision No. 12 with date 19. 10. 2007 (see Enclosure)
    - note this revision into the List of Revisions
  - b) In the Z 143 L aircraft Flight Manual (DOC.No.005.012) – English version:
    - remove old pages: 0-1; 0-9; 0-10; 0-11; 01-12; 0-15; 1-3; 2-4; 2-5; 2-9b; 2-13; 2-14; 2-16; 2-20; 4-6 (S/N 0022); 4-6 (S/N 0023); 4-8 (S/N 0022); 4-8 (S/N 0023); 6-16; 6-17; 6-18; 6-19; 6-20; 6-21; 6-22; 6-23; 6-24; 6-25; 7-19; 8-3; 8-4; 8-9 (S/N 0022); 8-9a (S/N 0022); 8-9b (S/N 0022); 8-9 (S/N 0023)
    - insert new pages marked by Revision No. 12 with date Oct. 19, 2007 (see Enclosure)
    - note this revision into the List of Revisions

- c) In the Z 143 L aircraft Flight Manual (DOC.No.005.012US) – US version:  
 - remove old pages: 0-1; 0-9; 0-10; 0-11; 0-12; 0-14; 1-3; 2-4; 2-5; 2-9b; 2-13; 2-14; 2-16; 2-20; 2-21; 2-22; 4-6 (S/N 0022); 4-6 (S/N 0023); 4-8 (S/N 0022); 4-8 (S/N 0023); 6-16; 6-17; 6-18; 6-19; 6-20; 6-21; 6-22; 6-23; 6-24; 6-25; 7-19; 8-3; 8-4; 8-9 (S/N 0022); 8-9a (S/N 0022); 8-9b (S/N 0022); 8-9 (S/N 0023)  
 - insert new pages marked by Revision No. 12 with date Oct. 19, 2007 (see Enclosure)  
 - note this into the List of Revisions
- d) In the Z 143 L aircraft Maintenance Manual (č.DOK.005.021.1) – Czech version:  
 - remove old pages: Title; 01-3; 01-11; 01-12; 01-13; 01-15; 01-16; 01-19; 01-20; 01-22; 01-23; 01-35; 05-20; 11-13; 24-10; 27-15; 32-36; 32-37; 32-39; 32-40; 32-41; 32-48; 32-51; 34-1; 55-20; 57-16; 57-17; 57-18  
 - insert new pages marked by Revision No. 10 with date 2007-11-20 (see Enclosure)  
 - note this revision into the List of Revisions
- e) In the Z 143 L aircraft Maintenance Manual (DOC.No.005.022.1) – English version:  
 - remove old pages: Title; 01-3; 01-11; 01-12; 01-13; 01-15; 01-16; 01-19; 01-20; 01-21; 01-22; 01-23; 01-35; 04-2; 05-20; 10-1; 11-13; 24-10; 24-19; 27-15; 32-36; 32-37; 32-39; 32-40; 32-41; 32-48; 32-51; 34-1; 51-4; 55-20; 57-16; 57-17; 57-18  
 - insert new pages marked by Revision No. 10 with date 2007-11-20 (see Enclosure)  
 - note this revision into the List of Revisions

**9. NECESSARY MATERIAL:**

New pages of accompanying documentation (see Enclosure).

**10. ENCLOSURES:**

New pages the Z 143 L aircraft Flight Manual (č.DOK.005.011), Czech version:  
 0-1; 0-9; 0-10; 0-11; 0-12; 0-13; 0-15; 1-3; 2-4; 2-5; 2-12; 2-13; 2-15; 4-6; 4-8; 6-16; 6-17; 6-18; 6-19; 6-20; 6-21; 6-22; 6-23; 6-24; 6-25; 7-19; 8-3; 8-4; 8-9; 8-9a; 8-9b

New pages of the Z 143 L aircraft Flight Manual (DOC.No.005.012), English version:  
 0-1; 0-9; 0-10; 0-11; 0-12; 0-15; 1-3; 2-4; 2-5; 2-9b; 2-13; 2-14; 2-16; 2-20; 4-6; 4-8; 6-16; 6-17; 6-18; 6-19; 6-20; 6-21; 6-22; 6-23; 6-24; 6-25; 7-19; 8-3; 8-4; 8-9; 8-9a; 8-9b

New pages of the Z 143 aircraft Flight Manual

(DOC. No. 005.012US), US version:

0-1; 0-9; 0-10; 0-11; 0-12; 0-14; 1-3; 2-4; 2-5; 2-9b; 2-13; 2-14;  
2-16; 2-20; 2-21; 2-22; 4-6; 4-8; 6-16; 6-17; 6-18; 6-19; 6-20; 6-21;  
6-22; 6-23; 6-24; 6-25; 7-19; 8-3; 8-4; 8-9; 8-9a; 8-9b

New pages of the Z 143 L aircraft Maintenance Manual

(č. DOK. 005.021.1), Czech version:

Title; 01-3; 01-11; 01-12; 01-13; 01-15; 01-16; 01-19; 01-20;  
01-22; 01-23; 01-35; 05-20; 11-13; 24-10; 27-15; 32-36; 32-37;  
32-39; 32-40; 32-41; 32-41a; 32-41b; 32-48; 32-51; 34-1; 55-20;  
57-16; 57-17; 57-18

New pages of the Z 143 L aircraft Maintenance Manual

(DOC. No. 005.022.1), English version:

Title; 01-3; 01-11; 01-12; 01-13; 01-15; 01-16; 01-19; 01-20;  
01-21; 01-22; 01-23; 01-35; 04-2; 05-20; 10-1; 11-13; 24-10;  
24-19; 27-15; 32-36; 32-37; 32-39; 32-40; 32-41; 32-41a; 32-41b;  
32-48; 32-51; 34-1; 51-4; 55-20; 57-16; 57-17; 57-18



.....  
**Dušan Totek**  
Chief Designer

**Contact address:**    **ZLIN AIRCRAFT a.s.**  
ZLIN Service  
765 81 Otrokovice  
Czech Republic