



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 143LSi/3a

Technical content of the document approved
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** March 15, 2008
- 2. MODEL AFFECTED:** All Z 143LSi aircraft.
- 3. SUBJECT:** Aircraft design modifications, formal adaptations of accompanying documentation.
- 4. CORRECTION:** Relevant revision of Z 143LSi Airplane accompanying documentation.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of this Bulletin.
- 6. PERFORMED BY:** Operator.
- 7. COSTS COVERED BY:** No will arise.
- 8. PROCEDURES:**
- a) In the Z 143LSi Airplane Flight Manual (č. DOK. Si 005.011) – Czech version:
 - remove old pages: title page; 0-8; 0-10; 0-12; 1-3; 2-1; 2-8; 2-13; 2-16; 2-17; 7-6; 7-8; 7-27; 8-3; 8-4
 - insert new pages marked by Revision No. 2 with date 2008-03-10 (see Enclosure)
 - note this revision into List of Revisions
 - b) In the Z 143LSi Airplane Flight Manual (DOC.No. Si 005.012) – English version:
 - remove old pages: title page; 0-8; 0-10; 0-12; 1-3; 2-1; 2-8; 2-13; 2-16; 2-17; 3-8; 7-6; 7-8; 7-27; 8-3; 8-4;
 - insert new pages marked by Revision No. 2 with date 2008-03-10 (see Enclosure)
 - note this revision into the List of Revisions

- c) In the Z 143LSi Airplane Maintenance Manual
(č. Dok. Si005.021.1– Czech version):
- remove old pages: Title page, 5, 6, 7, 8, 9, 10, 05-20, 11-3, 11-4, 11-5, 11-7, 11-10, 11-11, 11-12, 11-13, 11-14, 28-18, 28-19, 28-23, 28-24, 31-3, 31-10, 31-13, 31-14, 61-page 1, 61-7, 61-8, 61-9, 61-10, 61-11, 61-12, 77-page 1, 77-3, 77-9, 77-11, 91-page 1, 91-1, 91-2, 91-3, 91-4, 91-5, 91-6, 91-7, 91-8, 91-9, 91-10, 91-11, 91-12, 91-13, 91-14, 91-15, 91-16, 91-17, 91-18, 91-19, 91-20, 91-21, 91-22,
CAUTION: pages 91-3 to 91-22 are valid for S/N 0042 only.
 - insert new pages marked by Revision No. 3 with date 2008-02-15 (see Enclosure)
 - note this revision into the List of Alterations.
- d) In the Z 143LSi Airplane Maintenance Manual
(DOC.No.Si005.022.1
- English version):
- remove old pages: Title page, 5, 6, 7, 8, 9, 10, 05-20, 11-3, 11-4, 11-5, 11-7, 11-10, 11-11, 11-12, 11-13, 11-14, 28-18, 28-19, 28-23, 28-24, 31-3, 31-10, 31-13, 31-14, 61-page 1, 61-7, 61-8, 61-9, 61-10, 61-11, 61-12, 77-page 1, 77-3, 77-9, 77-11, 91-page 1, 91-1, 91-2, 91-3, 91-4, 91-5, 91-6, 91-7, 91-8, 91-9, 91-10, 91-11, 91-12, 91-13, 91-14, 91-15, 91-16, 91-17, 91-18, 91-19, 91-20, 91-21, 91-22
CAUTION: pages 91-3 to 91-22 are valid for S/N 0042 only.
 - insert new pages marked by Revision No. 3 with date 2008-02-15 (see Enclosure)
 - note this revision into the List of Alterations.
- e) Order new placard with design speeds (AFM page 2-17) at aircraft manufacturer and stick it on cockpit glass instead of the original one.

9. NECESSARY MATERIAL:

New pages of the Z 143LSi Airplane accompanying documentation (see Enclosure).
New placard with design speeds.

10. ENCLOSURE:

New page of the Z 143LSi Airplane Flight Manual (č. DOK. Si 005.011 – Czech version):
title page; 0-8; 0-10; 0-12; 1-3; 2-1; 2-8; 2-13; 2-16; 2-17; 7-6; 7-8; 7-27; 8-3; 8-4

New pages of the Z 143LSi Airplane Flight Manual (DOC.No. Si 005.012 – English version):
title page; 0-8; 0-10; 0-12; 1-3; 2-1; 2-8; 2-13; 2-16; 2-17; 3-8; 7-6; 7-8; 7-27; 8-3; 8-4

MANDATORY SERVICE BULLETIN Z 143 LSi/3a

New pages of the Z 143LSi Airplane Maintenance Manual

(č. Dok. Si005.021.1 - Czech version):

title page, 5, 6, 7, 8, 9, 10, 05-20, 11-3, 11-4, 11-5, 11-7, 11-10, 11-11, 11-11A, 11-11B, 11-12, 11-13, 11-14, 11-15, 11-16, 28-18, 28-19, 28-23, 28-24, 31-3, 31-10, 31-13, 31-14, 61-page 1, 61-7, 61-8, 61-9, 61-10, 61-11, 61-12, 77-page 1, 77-3, 77-9, 77-9A, 77-9B, 77-11, 91-page 1, 91-1, 91-2, 91-3, 91-4, 91-5, 91-6, 91-7, 91-6A, 91-7A, 91-8, 91-9, 91-10.

New pages of the Z 143LSi Airplane Maintenance Manual

(Doc. No. Si005.022.1 - English version):

Title page, 5, 6, 7, 8, 9, 10, 05-20, 11-3, 11-4, 11-5, 11-7, 11-10, 11-11, 11-11A, 11-11B, 11-12, 11-13, 11-14, 11-15, 11-16, 28-18, 28-19, 28-23, 28-24, 31-3, 31-10, 31-13, 31-14, 61-page 1, 61-7, 61-8, 61-9, 61-10, 61-11, 61-12, 77-page 1, 77-3, 77-9, 77-9A, 77-9B, 77-11, 91-page 1, 91-1, 91-2, 91-3, 91-4, 91-5, 91-6, 91-7, 91-6A, 91-7A, 91-8, 91-9, 91-10.



.....
Ing. Dušan Totek
Chief Designer

CONTACT ADDRESS: **ZLIN AIRCRAFT a.s.**
ZLIN Service
765 81 Otrokovice
Czech Republic