



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 242L/14a

1. MODELS AFFECTED: All Z 242L aircraft provided with english version of following Manuals:

1. Airplane Flight Manual, Doc. No. 003.012
2. Maintenance Manual, Vol. I, Doc. No. 003.022

2. SUBJECT: Removal of formal and syntactic faults in the Z 242L Airplane Flight Manual and the Maintenance Manual - Vol. I. The faults were found out by the aircraft operators and the aircraft manufacturer.

3. CORRECTION: Replace the following pages of the Z 242L AFM and MM - Vol. I. by the new ones, enclosed to this Bulletin.

1. The Z 242L Airplane Flight Manual, Doc. No. 003.012:

a) Remove old pages:

0-1, 0-3, 0-5/0-6, 1-1, 1-3/1-4, 1-5/1-6,
1-19/1-20, 1-23/1-24, 1-25/1-26, 2-1, 2-7/2-8,
2-9/2-10, 2-11/2-12, 2-13/2-14, 2-17/2-18,
2-23, 3-1, 3-3/3-4, 3-11/3-12, 3-13, 4-1,
4-11/4-12, 4-15/4-16, 4-17/4-18, 4-23/4-24,
4-27/4-28, Fig. 9/10 Chapter 4, 5-1,
5-9/5-10, 5-11/5-12, 5-17/5-18, 5-19/5-20,
5-21, 6-1, 6-3/6-4, 6-5/6-6, 6-7/6-8,
6-13/6-14, 7-1, 7-3, 7-9.

b) Insert new pages dated February 1, 1995:

0-1/0-2, 0-3/0-4, 0-5/0-6, 1-1/1-2, 1-3/1-4,
1-5/1-6, 1-19/1-20, 1-23/1-24, 1-25/1-26,
2-1/2-2, 2-7/2-8, 2-9/2-10, 2-11/2-12,
2-13/2-14, 2-17/2-18, 2-23/2-24, 3-1/3-2,
3-3/3-4, 3-11/3-12, 3-13/3-14, 4-1/4-2,
4-11/4-12, 4-15/4-16, 4-17/4-18, 4-23/4-24,
4-27/4-28, Fig. 9/10 Chapter 4, 5-1/5-2,
5-9/5-10, 5-11/5-12, 5-17/5-18, 5-19/5-20,
5-21/5-22, 6-1/6-2, 6-3/6-4, 6-5/6-6,
6-7/6-8, 6-13/6-14, 7-1/7-2, 7-3/7-4,
7-9/7-10.

2. The Z 242L Maintenance Manual - Vol. I, Doc. No. 003.022:

a) Remove old pages:


0-3/0-4, 0-5/0-6, 5-3/5-4, 6-23/6-24, 9-1/9-2

b) Insert new pages dated February 1, 1995:

0-3/0-4, 0-5/0-6, 5/3/5-4, 6-23/6-24,
6-24a/6-24b, 6-29/6-30, 7-1/7-2, 9-1/9-2

- 2 -

4. TIME OF COMPLIANCE: In operation, immediately after receipt of this Bulletin.
5. CORRECTION
PERFORMED BY: The user.
6. EXPENSES COVERED BY: No expenses arise.
7. NECESSARY MATERIAL: New pages of the Z 242L AFM and MM - Vol. I enclosed to the Bulletin and delivered by the manufacturer.
8. PROCEDURE: Replace old pages by the new ones and carry out the entry into the Log of Revisions.
9. THIS BULLETIN IS EFFECTIVE FROM THE DATE OF APPROVAL BY THE CIVIL AVIATION INSPECTORATE.
10. ENCLOSURES: New pages of the Z 242L Flight Manual and the Z 242L Maintenance Manual dated February 1, 1995.


Ing. Antonin Partika
.....
Manufacturer's
Representative


Ing. Milan Vyhnálek
.....
CAI Representative

9.3.1995
.....
Date of approval by the CAI

CONTACT ADDRESS: **ZLIN AIRCRAFT a.s.**
ZLIN SERVICE
765 81 OTROKOVICE
CZECH REPUBLIC