



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY BULLETIN Z 242L/ 36a

Engineering Aspect are
CAA Approved

1. **DATE:** March 20, 2000
2. **MODELS AFFECTED:** All ZLIN Z 242L Aircraft.
3. **SUBJECT:** Formal adaptations, reminder from aircraft operation near of the user and unification of the Z 242L Maintenance Manual Vol.-I and Vol.-II in Czech and English version.
4. **CORRECTION:** In the Z 242L Maintenance Manual Vol.-I (DOC. No. 003.022.1), Vol.-II (DOC. No. 003.032.1) – replace pages, which are included as an Enclosure of this Bulletin.
5. **TIME OF COMPLIANCE:** Immediately after receipt of Bulletin.
6. **CORRECTION PERFORMED BY:** Operator.
7. **EXPENSES COVERED BY:** No expenses will arise.
8. **PROCEDURE:**
 - a) In the Z 242L Maintenance Manual Vol.-I
Remove old pages: 0-2, 0-3, 0-4, 0-5, 1-5, 2-14, 2-15, 2-22, 2-23, 2-34, 2-38, 2-51, 2-54, 2-55, 2-61, 2-63, 2-67, 3-8, 3-9, 3-12, 4-6, 4-10, 4-12, 4-13, 4-17, 4-18, 5-3, 5-4, 5-5, 5-6, 5-9, 5-10, 5-11, 5-13, 5-17, 5-18, 5-21, 6-8, 6-11, 6-19, 7-1, 7-8, 7-10, 7-13, 7-14, 7-18, 7-21, 7-22, 7-25, 7-26, 7-27, 7-29, 7-30, 7-31, 7-33, 7-34.
Insert new pages marked with REVISION No.5, Mar 20, 2000 (see Enclosure).
 - b) In the Z 242L Maintenance Manual Vol.-II
Remove old pages: 0-3, 0-4, 0-5, 0-7, 1-14, 6-69, 6-91, 6-115, 7-27 to 7-40.
Insert new pages marked with REVISION No.1, Mar 20, 2000 (see Enclosure)
 - c) Note this revision into the List of Revisions
9. **NECESSARY MATERIAL:** New pages of the Z 242L Maintenance Manual Vol. I., II. (see Enclosure).

10. ENCLOSURE:

New pages in the Z 242L- Maintenance Manual Vol.-I: 0-2, 0-3, 0-4, 0-5, 1-5, 2-14, 2-15, 2-22, 2-23, 2-34, 2-38, 2-51, 2-54, 2-55, 2-61, 2-63, 2-67, 3-8, 3-9, 3-12, 4-6, 4-10, 4-12, 4-13, 4-13a, 4-13b, 4-17, 4-18, 5-3, 5-4, 5-5, 5-6, 5-9, 5-10, 5-11, 5-13, 5-17, 5-18, 5-21, 5-21a, 5-21b, 6-8, 6-11, 6-19, 7-1, 7-8, 7-10, 7-13, 7-14, 7-18, 7-21, 7-22, 7-25, 7-26, 7-27, 7-29, 7-30, 7-31, 7-33, 7-34.

New pages in the Z 242L- Maintenance Manual Vol.-II: 0-3, 0-4, 0-5, 0-7, 1-14, 6-69, 6-91, 6-115, 7-27, 7-28.


.....
Ing. Lubomír Hušený
Chief Designer

CONTACT ADDRESS: ZLIN AIRCRAFT a.s.

Obchodne technicke sluzby
765 81 Otrokovice
Czech Republic