

## ZLIN AIRCRAFT a.s.

Letiště 1578, 765 81 Otrokovice, Czech Republic

e-mail: zlinservice@zlinaircraft.eu http://www.zlinaircraft.eu



MANDATORY BULLETIN Z 37T/13a

Z 137T/ 2a

1. AFFECTED AIRCRAFT: All Z 37T, Z 137T and Z 137T-2 aircraft

through S/N 050 inclusive.

2. SUBJECT: Increase of the operational reliability of the "Central electronic limiter"

LUN 5260.03 and avoidance of possible contingent spontaneous interference

with the engine run.

3. CORRECTION: All units LUN 5260.03 must be modified.

The modification shall be performed by MESIT Inc., 686 49 Uherské Hradiště,

Czech Republic.

For this purpose:

a) Each operator of affected aircraft shall send immediately after receipt of this Bulletin:

- all LUN 5260.03 units from the spare

parts stock

- LUN 5260.03 units removed from the aircraft that are temporarily out of operation

to be modified on the above adress.

b) After return of the modified LUN 5260.03 units the operator shall replace the non-modified ones on the aircraft in operation by the returned modified units. So far the operator shall send the removed units to be modified as in a).

The modified units shall be identified on the front cover by the Type Identification No. LUN 5260.03 underlined with the white colour. The operation of the non-modified units LUN 5260.03 on the aircraft after October 1, 1994 is prohibited.

4. TIME OF COMPLIANCE: acc. paragraph 3a) Immediately after receipt this Bulletin acc. paragraph 3b) Not later than by Septem-

acc. paragraph 3b)Not later than by September 30, 1994.

5. PERFORMED BY: Removal and installation of the unitsthe Operator.

Modification of units - MESIT Inc. Download date: 14.03.2013

6. EXPENSES COVERED BY: The cost of modification of LUN 5260.03
units, the service life (i.e. 6000 flight
hours or 6 calender years since installation)
of which is not expired, shall be covered
by the manufacturer of the unit. The cost
of additional repairs, which may be found
as necessary and which do not consist with
the modification, shall cover the operator.

7. NECESSARY MATERIAL: No material necessary.

8. PROCEDURE:

Remove and install the units in accordance with the manual "Z 37T (Z 137T) INSTRUMENTS AND APPLIANCES".

9. THE BULLETIN COMES IN FORCE FROM THE DATE OF APPROVAL BY THE CIVIL AVIATION INSPECTORATE OF THE CR.

Antonín Partika Manufacturer s Representative Vladimír Příhoda
Civil Aviation Inspectorate
of the Czech Republic

1.7.1994

Date of Approval by the CAI