



**ZLIN AIRCRAFT a.s.**  
Letiště 1578, 765 81 Otrokovice,  
Czech Republic  
e-mail: [zlin-service@zlinaircraft.eu](mailto:zlin-service@zlinaircraft.eu)  
<http://www.zlinaircraft.eu>

**MANDATORY**

**SERVICE  
BULLETIN**

**MANDATORY BULLETIN Z 50/45a**  
**Z 50M/17a**

Engineering aspect  
CAA approved

- 1. DATE:** 10.5.2001
- 2. MODEL AFFECTED:** All Z 50L, Z 50LA, Z 50LS, Z 50LX, Z 50M.
- 3. SUBJECT:** Change of engine and propeller maintenance. Change of references on the accompanying documentation of engine and propeller manufacturer's.
- 4. CORRECTION:** In the accompanying documentation series Z 50 aircrafts replace pages which are included as an Enclosure of this bulletin.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of bulletin.
- 6. CORRECTION PERFORMED BY:** Operator.
- 7. EXPENSES COVERED BY:** No expenses will arise.
- 8. PROCEDURE:**
- a) **In the „Z 50L, Z 50LA Technical Manual“ (english version)**
    - remove old pages: 8, 13, 48, 69, 86, 90, 92, 95, 96, 97, 98, 99, 100, 100A, 104, 105, 107, 108, 109
    - insert new pages with marked Rev. 10.5.2001 (see Enclosure)
    - note this revision into the List of revisions.
  - b) **In the „Z 50LS Technical Manual“ (english version)**
    - remove old pages: 8, 13, 48, 69, 86, 91, 92, 97, 100, 101, 102, 103, 104, 105, 106, 110, 111, 114, 115, 116
    - insert new pages with marked Rev. 10.5.2001 (see Enclosure)
    - note this revision into the List of revisions.
  - c) **In the „Z 50LS Technische Beschreibung und bedienungsanleitung“ (germany version)**
    - remove old pages: 8, 13, 48, 69, 87, 92, 96, 99, 100, 101, 102, 103, 104, 108, 111, 112, 113, 114
    - insert new pages with marked Rev. 10.5.2001 (see Enclosure)
    - note this revision into the List of revisions.
  - d) **In the „Z 50LX Technical Manual“ (english version)**
    - remove old pages: 8, 13, 48, 69, 86, 91, 92, 97, 100, 101, 102, 103, 104, 105, 106, 110, 111, 114, 115, 116
    - insert new pages with marked Rev. 10.5.2001 (see Enclosure)
    - note this revision into the List of revisions.

e) **In the „Z 50M Technical Manual“ (english version)**

- remove old pages: 0-3, 0-5, 1-10, 2-39, 2-58, 3-17, 3-18, 3-19, 3-22, 3-23, 3-24, 3-25, 3-27, 3-29, 3-30, 3-31
- insert new pages with marked Rev. May 10/01 (see Enclosure)
- note this revision into the List of revisions.

**9. NECESSARY MATERIAL:** New pages for aircraft accompanying documentaion changes (see Enclosure).

**10. ENCLOSURE:**

New pages of Z 50L, Z 50LA Technical Manual:

8, 13, 48, 69, 86, 90, 92, 95, 96, 97, 98, 99, 100, 100A, 104, 105, 107, 108, 109.

New pages of Z 50LS Technical Manual:

8, 13, 48, 69, 86, 91, 92, 97, 100, 101, 102, 103, 104, 105, 106, 110, 111, 114, 115, 116.

New pages of Z 50LS Technische Beschreibung und bedienungsanleitung:

8, 13, 48, 69, 87, 92, 96, 99, 100, 101, 102, 103, 104, 108, 111, 112, 113, 114

New pages of Z 50LX Technical Manual:

8, 13, 48, 69, 86, 91, 92, 97, 100, 101, 102, 103, 104, 105, 106, 110, 111, 114, 115, 116.

New pages of Z 50M Technical Manual:

0-3, 0-5, 1-10, 2-39, 2-58, 3-17, 3-18, 3-19, 3-22, 3-23, 3-24, 3-25, 3-27, 3-29, 3-30, 3-31



.....  
Dipl. Eng. Dušan TOTEK  
Chief designer

**Contact address:**

**ZLIN AIRCRAFT a.s.**  
Obchodne technicke sluzby  
765 81 Otrokovice  
Czech Republic