T / +420 577 120 800 F / +420 266 013 830



SERVICE LETTER No. L 141

DATE:	August 17, 2022
TO:	Ministry of Defense of Bulgaria
MODEL AFFECTED:	Z 242 L aircraft, S/N: 0852, 0853, 0854, 0855
SUBJECT:	Permission of disassembly and aircraft operation

Aircraft manufacturer ZLIN AIRCRAFT a.s. **permits** disassembling of the nose landing gear leg cover located in the lower engine cover, Drwg. No. Z242.6510-00.09 (see Figure No. 2, item No. 2) and further operation of aircraft without this cover.

This nose landing cover (on the lower engine cover) serves to covering and sealing the area around the nose landing gear leg.





Fig. No. 1 – Cover of nose landing gear leg, Drwg. No. Z242.6510-00.09

2LIN AIRCRAFT a.s. IČO / ID: 278 94 134

Letiště 1887 765 02 Otrokouice






Fig. No. 2 .- Location of the cover on the aircraft (item No. 2)

TIME OF COMPLIANCE:	Immediately after receipt of this Service Letter
PROCEDURES:	Disassemble the cover of the nose landing gear leg. (<i>Drwg. No. Z242.6510-00.09</i>). Note this disassembly into the aircraft log book.
NECESSARY MATERIAL:	
ENCLOSURES:	
Elaborated by:	Lubomír Januška

Head of Documentation and Normalization Dept.